

# Oil Field Environmental Incident Summary

**Incident:** 20151027073822

**Date/Time of Notice:** 10/27/2015 07:38

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** ALAN 1-06H

**Field Name:** PARSHALL

**Well File #:** 16577

**Date Incident:** 10/26/2015

**Time Incident:** 08:40

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 152

**Rng:** 90

**Sec:** 6

**Qtr:** SW SE

**Location Description:**

**Submitted By:** Keith Kallberg

**Received By:**

**Contact Person:** Keith Kallberg  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	5	Barrels	5	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/8/2016

**Clean Up Concluded:** 11/2/2015

**Risk Evaluation:**

Low

**Areal Extent:**

**Potential Environmental Impacts:**

NA

**Action Taken or Planned:**

The well was shutin stopping the release. Vac truck was used to remove the free fluid and a cleanup crew will scrape and remove the affected material after repairs to the treater have been completed. Outside affected area to the SW was scraped and put inside the treater berm containment and will be removed.

**Wastes Disposal Location:** Fluids taken to Lokken SWD and the solids will be taken to Clean Harbors.

**Agencies Involved:**

**Updates**

---

**Date:** 10/27/2015 **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to equipment failure, remained on location according to the report. NDIC retains oversight.